



Fuel filler hose

Classification	Mandatory
Applicability	All Europa aircraft
Compliance	Before the next flight, and then every 10 flying hours until replacement action is complete.

Introduction

Isolated cases have been reported concerning degradation of the material of the fuel filler hose liner.

The suppliers of this component have established that the material is not sufficiently fuel proof in the long term, and all fuel filler hoses which have been delivered before the date of this bulletin will be replaced free of charge.

Action

1. Inspect the connections of the fuel filler hose to the fuel filler cap and to the fuel tank for structural integrity.
2. Inspect the fuel filter for signs of perished rubber, and clean as necessary.
3. On receipt of the replacement filler hose, remove and discard the original hose, fit the replacement, and test for leaks.

Note: *Over 250 hoses have been delivered to Europa builders. The supplier will replace these as fast as possible, but this will inevitably take some time. Replacement hoses will be sent out automatically, and it will not be necessary for recipients of this Bulletin to order new hoses.*