
Main gear leg sockets MG03P/S

Applicability: Components delivered between the beginning of December 2000 and the end of May 2001.

Introduction

It has been established that a batch of components of the above part number included some which had the hole at the top drilled incorrectly, such that it did not line up with the equivalent hole in the main gear leg. Figure 1 shows a view of the socket and the hole concerned.




Fig 1. Main gear leg socket showing mounting hole.

Action

1. Trial fit the main gear legs to the sockets to establish whether the AN5-21A bolt will pass through both components.
2. If the components are defective, return them to Europa for free replacement.